03-06-06 10,621,625.

RNES DICKE



March 3, 2006

Express Mail Label No. EV 853 855 754 US

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re:

4

U.S. Patent No. 6,983,618

Issued January 10, 2006

Method and Apparatus for Refrigeration

System Control Having Electronic **Evaporator Pressure Regulators**

Abtar Singh et al, Inventor

Certificate

MAR 0 9 2006

of Correction

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office and the Patent Office. Our check for \$100.00 is enclosed.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 8, line 9 of the application.

The second error appears on page 10, line 11 of the application.

The third error appears on page 11, line 18 (first occurrence) of the application.

The fourth error appears on page 16, line 9 (second occurrence) of the application.

The fifth error appears on page 4, line 8, claim 66 in the amendment dated August 23, 2004.

03/08/2006 BABRAHA1 00000066 6983618

853 855 754

01 FC:1811

100.00 OP

FOR COURIER DELIVERY ONLY Harness, Dickey & Pierce, P.L.C. Attorneys and Counselors 5445 Corporate Drive Troy, Michigan 48098 248.641.1600

9 2000 . MAR

CABLE Patents Troy, Michigan Telex No. & Reply 287637 Harness UR Telefacsimile 248.641.0270

Metropolitan

P.O. Box 828

Detroit, MI St. Louis, MO

Bloomfield Hills, MI 48303 U.S.A.

Washington, D.C.

moordpyrmm

The sixth error appears on page 5, line 6, claim 74 in the amendment dated May 6, 2005.

The seventh error appears on page 7, line 8, claim 89 in the amendment dated May 6, 2005.

Please certify the enclosed Certificate of Correction and return same to us.

Very truly yours,

Michael Malinzak

Registration No. 43770 (Attorney for Applicant)

MM/d 4731-000001/COD

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,983,618

DATED: January 10, 2006

INVENTOR(S): Abtar Singh; Jim Chabucos; Paul Wickberg; John Wallace

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 21, ";" should be -- . --.

Column 5, line 19, "an" should be -- and --.

Column 5, line 58 (first occurrence), after "may" delete "be".

Column 7, line 65 (second occurrence), after "detector", "26" should be -- 66 --.

Column 14, line 27, "regulator" should be -- regulators --.

Column 14, line 40, "far" should be -- for --.

Column 16, line 1, "feast" should be -- least --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce P.L.C. P.O, Box 828 Bloomfield Hills, MI 48303

PATENT NO. 6,983,618

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

(Also Form PTO-1050)

PATENT NO: 6,983,618

DATED: January 10, 2006

INVENTOR(S): Abtar Singh; Jim Chabucos; Paul Wickberg; John Wallace

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

CERTIFICATE OF CORRECTION

Column 4, line 21, ";" should be -- . --.

Column 5, line 19, "an" should be -- and --.

Column 5, line 58 (first occurrence), after "may" delete "be".

Column 7, line 65 (second occurrence), after "detector", "26" should be -- 66 --.

Column 14, line 27, "regulator" should be -- regulators --.

Column 14, line 40, "far" should be -- for --.

Column 16, line 1, "feast" should be -- least --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce P.L.C. P.O, Box 828 Bloomfield Hills, MI 48303

PATENT NO. 6,983,618

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

